



Fig. A Photograph of Cracked battery container (observation direction : b)





Fig. B Photograph of This invention's battery container (observation direction : b)

These battery containers are analyzed by TOSHIBA NANOANALYSIS Corp. in 12/Mar/2004

These photos are taken by metallurgical microscope